

# Oil Field Environmental Incident Summary

**Incident:** 20160227150448      **Date/Time of Notice:** 02/27/2016 15:04

**Responsible Party:** WHITING OIL AND GAS CORPORATION

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** GULLIKSON 44-34H

**Field Name:** GLASS BLUFF

**Well File #:** 32044

**Date Incident:** 2/27/2016      **Time Incident:** 10:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 152

**Rng:** 103

**Sec:** 34

**Qtr:** SE SE

**Location Description:**

**Submitted By:** Corissa Zimmer

**Received By:**

**Contact Person:** Corissa Zimmer  
1700 BROADWAY STE 2300  
DENVER, CO 80290

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3	Barrels			3	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 3/16/2016

**Clean Up Concluded:** 2/28/2016

**Risk Evaluation:**

None noted.

**Areal Extent:**

***Potential Environmental Impacts:***

None noted.

***Action Taken or Planned:***

The hammer union was tightened and a hydrovac truck will clean up the fluid. Whiting will check the hammer unions at this facility regularly

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 2/29/2016    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Souder, Taylor

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

According to the incident report, the release was contained. NDIC takes oversight.